




## MFT0-125 Repair Kit

- (1) Bimetal Element Part Number M0313
- (1) Float Assembly Part Number M1299
- (1) Valve Assembly Part Number 0202
- (1) Valve Seat Part Number M0101
- (1) Cover Gasket Part Number M0151W
- (1) Strainer Part Number M0357
- \* (2) Pivot Pin Plug Part Number M1210
- \* (2) Pivot Plug Washer Part Number M-2001

\*Optional Parts



\*Tools required for repair:  
Stem Key Part Number L99001

Velan recommends setting trap with digital calibrator, please call the number listed below if you require assistance