




## MFT2-200 Repair Kit

- (1) Bimetal Element Part Number M3163
- (1) Float Assembly Part Number 1298
- (1) Valve Assembly Part Number 0207
- (1) Valve Seat Part Number 1607L
- (1) Cover Gasket Part Number M4100W
- (1) Strainer Part Number M4300
- \* (2) Pivot Pin Plug Part Number 1197
- \* (2) Pivot Pin Washers Part Number 2001

\*Optional Parts



\*Tools required for repair:  
Stem Key Part Number L99001

Velan recommends setting trap with digital calibrator, please call the number listed below if you require assistance