




## N-150 Repair Kit

- (1) Bimetal Element Part Number 2180
- (1) Cover Gasket Part Number G27/KAMM
- (1) Strainer Part Number 2226
- (1) Valve Assembly Part Number 1730
- (1) Valve Seat Part Number 1603L
- (2) Bottom Plug Gaskets Part Number 1681-4-L



\*Tools required for repair:  
Stem Key Part Number L99002

Velan recommends setting trap with digital calibrator, please call the number listed below if you require assistance