




N-1500 Repair Kit

- (1) Bimetal Element Part Number 5124
- (1) Cover Gasket Part Number G27/KAMM
- (1) Strainer Part Number 2226
- (1) Valve Assembly Part Number 1733
- (1) Valve Seat Part Number 1608-WG
- (2) Bottom Plug Gaskets Part Number 1681491



*Tools required for repair:

Stem Key Part Number L99002

Seat Locating Tool Part Number L99045

Velan recommends setting trap with digital calibrator, please call the number listed below if you require assistance