




N-2500 Repair Kit

- (1) Bimetal Element Part Number 5120
- (1) Cover Gasket Part Number 2379
- (1) Strainer Part Number 2227
- (1) Valve Assembly Part Number 1759-A
- (1) Valve Seat Part Number 1609WG

*Note, N-2500 plugs are welded, there are no plug gaskets.



*Tools required for repair:
Stem Key Part Number L99002
Seat Locating Tool Part Number L99046/1

Velan recommends setting trap with digital calibrator, please call the number listed below if you require assistance

