




N-675 Repair Kit

- (1) Bimetal Element Part Number 5112
- (1) Cover Gasket Part Number G27/KAMM
- (1) Strainer Part Number 2226
- (1) Valve Assembly Part Number 1733
- (1) Valve Seat Part Number 1609WG
- (2) Bottom Plug Gaskets P/N 1681-4-L



*Tools required for repair:

Stem Key Part Number L99002

Seat Locating Tool Part Number L99046

Velan recommends setting trap with digital calibrator, please call the number listed below if you require assistance