




MFT4-200 Repair Kit

- (1) Bimetal Element Part Number 5617
- (1) Float Assembly P/N 1287
- (1) Valve Assembly Part Number 0206
- (1) Valve Seat Part Number 1608L
- (1) Cover Gasket Part Number M2302
- (1) Strainer Part Number M0351
- * (2) Pivot Pin Plug Part Number 1192
- * (2) Pivot Plug Washer Part Number 2001

*Optional Parts



*Tools required for repair:
Stem Key Part Number L99001

Velan recommends setting trap with digital calibrator, please call the number listed below if you require assistance