




SP7-600 Repair Kit

- (1) Pilot Valve Seat P/N 1604 (SCR) –OR–
- (1) Pilot Valve Seat P/N 1654 (WLD)
- (1) Liner Valve Assembly P/N 1714
- (1) Pilot Valve Assembly P/N 1770A
- (2) SP Top Cover/Strainer Gasket P/N 2340
- (1) SP Liner Gasket P/N 2355
- (1) SP Strainer P/N 2234
- (1) SP-7 Pilot Cage P/N 5117
- (1) SP Temperature Controller Gasket P/N 2350/NA
- (1) SP-7 Temperature Controller P/N 2760



**Tool Required for Repair: SP STEM KEY, P/N L99003